




Do not overfill



Stack correctly



Stack correctly



Wear face shield



Respect security specification



Wear safety gloves



Wear safety glasses



Wear a dust mask



Use ear muffs






Respect factory Quality rules



Service repair and adjustment by qualified people only



Do not leave running machines unattended



Disconnect electrical machines before servicing



Doors must remain closed



No dust

No dirt

No contamination



Read machine instructions



Small details make good quality



Clean room,  
no  
contamination







Use cotton gloves  
for silver, gold and  
plated parts



Wear safety helmet



Wear protection



Lift correctly



Read instructions



Read operator  
manual



White room,  
wear special  
shoes and clothes



When welding,  
wear special  
mask and clothes



Wear welding mask

